

## FIELD INSPECTION

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Matthew Grant
<b>Inspection Date:</b>	Wednesday, April 17, 2019	<b>Project Contact:</b>	Brian Clauto
<b>Spread: Montgomery County MP227-228 St#12009-12035</b>	Spread H	<b>Weather (Wet/Dry/Rain):</b>	Dry

**STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Clearing

☐ Rough Grading

☐ Trench Excavation

☐ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration

☐ Final Grading & Stabilization

☒ Other: Dormant

- |   |   | Yes                                 | No                                  | N/A                      |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed?   | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |


**Comments:**

- Inspected designated streams and wetlands included: S-G36, S-G39, S-G40, S-G26, S-G38 ECD were in place near all the streams / wetlands, no impacts were observed at the time of the inspection.
- St#12009-12035 controls between these stations were in place and functioning.

**Recommended Corrective Action:** N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:  Date: 5-6-19

## FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, April 17, 2019

Fig. 1 Designated stream S-G36

### South East Elevation

☉ 325°NW (T) ☉ 37°16'6"N, 80°18'48"W ±164.1ft ▲ 1503ft



Fig. 2 Designated stream S-G39

### North West Elevation

☉ 156°SE (T) ☉ 37°15'54"N, 80°18'31"W ±32.8ft ▲ 1670ft



Fig. 3 Designated stream S-G40

### North West Elevation

☉ 142°SE (T) ☉ 37°15'54"N, 80°18'27"W ±164.1ft ▲ 1420ft



Fig. 4 Designated stream S-G38

### North West Elevation

☉ 125°SE (T) ☉ 37°17'13"N, 80°17'43"W ±11289.9ft ▲ 1749ft

